





Version	Date	Change/a	additions additions	
01.28.10	Jul, 5th 2019	■ Fixed bug	g in Channel Expansion/TCHub firmware that caused blinking in Race Studio 3 Live Measures	
		External m	nodules	
		<b>40.63</b>	Channel Expansion/TC Hub	
			■ Fixed bug that caused blinking in Race Studio 3 Live Measures	
01.28.08	Jun, 12th 2019	■ Fixed CAI	N protocols with multiplex frames	
		External modules		
		<b>40.62</b>	Channel Expansion/TC Hub	
		<b>35.61</b>	GPS Module	
01.28.03	Feb, 12th 2019	■ Fixed disp	olay artifacts in measures value cleaning	
		External m	nodules	
		<b>01.26.49</b>		
			<ul><li>Measures timeout improved</li><li>Spansion support</li></ul>	
			■ Fix data recall synchronization issue	
		<b>01.26.48</b>	Memory Module	
			■ Improved support for various models of SD cards	
		<b>02.26.51</b>	Shift Light Module  Fixed issues with some ECUs	
		NIl		
		No change:	s for the other modules	







Version	Date	Change/additions
01.26.46	Dec, 5th 2018	Added management of Shift Light Module
		External modules
		No changes
01.26.42	Oct, 30th 2018	Support for CAN Optical Lap (IRM_42)
		Set Brightness Mode using Remote button fix
		CAN Bus 120 Ohm Resistor setting fix
		Optical Beacon blind time fix
		External modules
		No changes
01.26.38	Oct, 5th 2018	Added possibility to force channels in Online
		<ul><li>Fixed bug on Digital output priority handling</li></ul>
		External modules
		No changes
01.26.28	Apr, 12th 2018	<ul> <li>Fixed bug in remote display configuration</li> </ul>
		External modules
		<b>01.26.22</b> Memory Module
		<b>01.26.28</b> GS-Dash
		■ 01.26.28 Formula Steering Wheel 3
		<b>35.58</b> GPS Module
		<b>25.47</b> Lambda
		<b>40.61</b> Channel Expansion/TC Hub
		<b>70.03</b> Remote buttons interface







Version	Date	Change/a	dditions	
01.26.25	Jan 11th 2018		when the Start Data Recording standard condition is configured: in some conditions not recorded data	
		Fixed bug in volume sensors with gallons unit measure		
		External m	odules	
		■ 01.26.22	Memory Module	
		■ 01.26.22	GS-Dash	
		■ 01.26.22	Formula Steering Wheel 3	
		■ 35.58	GPS Module	
		<b>25.47</b>	Lambda	
		<b>40.61</b>	Channel Expansion/TC Hub	
		<b>70.03</b>	Remote buttons interface	
01.26.24	Nov 14th 2017	■ Fix lockup	at power up for some devices	
		External m	odules	
		■ 01.26.22	Memory Module	
		■ 01.26.22	GS-Dash	
		■ 01.26.22	Formula Steering Wheel 3	
		■ 35.58	GPS Module	
		<b>25.46</b>	Lambda	
		<b>40.60</b>	Channel Expansion/TC Hub	
		<b>70.03</b>	Remote buttons interface	
01.26.23	Oct 24th 2017	■ Support fo	or CAN builder ID mask feature	
		Consume	d fuel channel	
			per wheel revolution setting not working for Speed1 or Speed2 digital inputs	
		Fix: wrong	g order of operands in bias math channel	
		External modules		
		■ 01.26.22	Memory Module	
		■ 01.26.22	GS-Dash	
		<b>01.26.22</b>	Formula Steering Wheel 3	
		■ 35.58	GPS Module	
		<b>25.46</b>	Lambda	
		<b>40.60</b>	Channel Expansion/TC Hub	
		<b>70.03</b>	Remote buttons interface	







Version	Date	Change/a	additions
01.26.14	Jul 7th 2017	Improved	d CAN management: more reliability in firmup and configuration transmission
		External m	nodules
		■ 01.26.14	Memory Module
		<b>01.26.14</b>	GS-Dash
		<b>01.26.14</b>	Formula Steering Wheel 3
		<b>35.58</b>	GPS Module
		<b>25.46</b>	Lambda
		<b>40.60</b>	Channel Expansion/TC Hub: minor bug fixed
		<b>70.03</b>	Remote buttons interface
01.26.08	Jun 20th 2017	= Momony	Module support
01.20.08	Juli 2011 2017	•	
		External m	
			Memory Module
		<b>=</b> 01.26.08	
			Formula Steering Wheel 3
		<b>35.58</b>	GPS Module
		<b>25.46</b>	Lambda Channel Supersian /TC Hubersian ben fixed
		<b>40.60</b>	Channel Expansion/TC Hub: minor bug fixed  Remote buttons interface
		<b>70.01</b>	Remote buttons interface
01.24.56	Jun 1st 2017	<ul><li>Fixed roll</li></ul>	ing lap time on GS-Dash and Formula Steering Wheel 3
		External m	nodules
		<b>01.24.56</b>	GS-Dash
		<b>01.24.56</b>	Formula Steering Wheel 3
		<b>35.58</b>	GPS Module
		<b>25.46</b>	Lambda
		<b>40.60</b>	Channel Expansion/TC Hub: minor bug fixed
		<b>= 70.01</b>	Remote buttons interface
01.24.54	May 19th 2017	= Includos	firmware GPS v 35.58.00 that fixes data synchronization with SmartyCam HD
01.24.54	Way 15th 2017		
		External m	
		<b>=</b> 01.24.54	
			Formula Steering Wheel 3
		<b>35.58</b>	GPS Module







Version	Date	Change/additions
		<b>25.46</b> Lambda
		■ 40.60 Channel Expansion/TC Hub: minor bug fixed
		■ 70.01 Remote buttons interface
01.24.52	May 18th 2017	<ul><li>Fixed GPS Data visualization on GS-Dash and Formula Steering Wheel 3</li></ul>
		External modules
		■ 01.24.52 GS-Dash
		■ 01.24.52 Formula Steering Wheel 3
		■ <b>35.56</b> GPS Module
		<b>25.46</b> Lambda
		■ 40.60 Channel Expansion/TC Hub: minor bug fixed
		■ <b>70.01</b> Remote buttons interface
01.24.45	Apr 19th 2017	<ul><li>Fixed bug in AiM digital speed channels when 'Ang Velocity' is selected (i.e. RPM setting)</li></ul>
		External modules
		<b>35.56</b> GPS Module
		■ <b>25.46</b> Lambda
		■ 40.56 Channel Expansion/TC Hub
		■ <b>70.01</b> Remote buttons interface
01.24.38	Apr. 5th 2017	<ul> <li>Support for Formula Steering Wheel 3 configuration</li> </ul>
	·	External modules
		■ 35.56 GPS Module
		■ 25.46 Lambda
		■ 40.56 Channel Expansion/TC Hub
		■ 70.01 Remote buttons interface
01.24.34	Mar 24th 2017	<ul> <li>Added GS-Dash management</li> </ul>
		Improved accelerometer support: better filtering and uniform sign convention on various devices
		External modules
		<b>35.56</b> GPS Module
		■ <b>25.46</b> Lambda
		■ 40.56 Channel Expansion/TC Hub
		■ 70.01 Remote buttons interface







Version	Date	Change/additions	
01.24.00	Jan 26th 2017	Fixed issue that caused CAN network malfunction when remote button device is in the network	
		External modules	
		<b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ 70.01 Remote buttons interface	
01.22.99	Jan 19th 2017	<ul> <li>Added management of GPS position accuracy measure for CAN output</li> </ul>	
		External modules	
		<b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ <b>70.01</b> Remote buttons interface	
01.22.94	Dec 5th 2016	■ No changes	
		External modules	
		<b>35.56</b> GPS Module	
		■ 25.46 Lambda: fixed bug that caused shifted lambda samples	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ 70.01 Remote buttons interface	
01.22.92	Nov 29th 2016	■ Fixed bug which prevented editing of Wi-Fi and User parameters from RS3	
		<ul> <li>Minor improvements</li> </ul>	
		External modules	
		■ 35.56 GPS Module: improvements in GPS measurements available to SmartyCam overlay	
		<b>25.44</b> Lambda	
		<b>40.56</b> Channel Expansion/TC Hub	
		<b>70.01</b> Remote buttons interface	







Version	Date	Change/additions		
01.22.86	Nov 15th 2016	Added IRM CAN LAP support		
		External modules		
		■ 35.54 GPS Module: improved satellites fix		
		<b>25.44</b> Lambda: added keep alive support		
		■ 40.56 Channel Expansion/TC Hub		
		■ <b>70.01</b> Remote buttons interface		
01.22.82	Oct 11th 2016	Speed up USB transfer		
		Fixed bug in GPS lap management that in some cases caused loss of laps detected		
		External modules		
		<b>35.50</b> GPS Module		
		<b>25.42</b> Lambda		
		■ 40.56 Channel Expansion/TC Hub: improved analogic channels acquisition		
		■ <b>70.01</b> Remote buttons interface		
01.22.74	Sep 15th 2016	■ Fixed alarms functionality based on acquisition channels under encryption		
		External modules		
		<b>35.50</b> GPS Module		
		<b>25.42</b> Lambda		
		■ 40.55 Channel Expansion/TC Hub		
		<b>70.01</b> Remote buttons interface		
01.22.60	Jul 25th 2016	■ Fixed: Wi-Fi troubles with TP-link routers		
		Fixed: alarm hysteresis condition		
		Minor bugfixes and improvements		
		External modules		
		<b>35.50</b> GPS Module		
		<b>25.42</b> Lambda		
		<b>40.55</b> Channel Expansion/TC Hub		
		■ <b>70.01</b> Remote buttons interface		







Version	Date	Change/additions		
01.20.68	Jul 1st 2016	■ Fixed: handling of enabling /disabling of CAN termination resistance		
		External modules		
		<b>35.50</b> GPS Module		
		25.42 Lambda (fixed issues with channels configured at 5Hz)		
		■ 40.55 Channel Expansion/TC Hub: improvement in measurements accuracy		
		■ <b>70.01</b> Remote buttons interface		
01.20.66	Apr 19th 2016	■ CAN output support		
		External modules		
		<b>35.50</b> GPS Module		
		25.42 Lambda (fixed issues with channels configured at 5Hz)		
		40.55 Channel Expansion/TC Hub: improvement in measurements accuracy		
		■ <b>70.01</b> Remote buttons interface		
01.20.63	Mar 11th 2016	<ul> <li>Fixed issue on ECU channels right after a configuration update</li> </ul>		
		Fixed issue in start reco via custom formula		
		External modules		
		<b>35.50</b> GPS Module		
		■ 25.42 Lambda (fixed issues with channels configured at 5Hz)		
		■ 40.54 Channel Expansion/TC Hub		
		■ <b>70.01</b> Remote buttons interface		
01.20.62	Mar 9th 2016	<ul> <li>Improvements in Wi-Fi and measurements for SmartyCam</li> </ul>		
		<ul><li>Fixed bug in Custom Position Sensor (the measure was multiplied by 1000)</li></ul>		
		External modules		
		■ <b>35.50</b> GPS Module		
		<b>25.40</b> Lambda		
		■ 40.54 Channel Expansion/TC Hub		
		■ <b>70.01</b> Remote buttons interface		
01.20.61	Feb 26th 2016	First production version		