



## MyChron5S Release history

| Version         | Date           | Change/additions   |
|-----------------|----------------|--|
| <b>02.36.80</b> | Sep, 14th 2021 | <ul style="list-style-type: none"><li>▪ Fixed bug that caused no laps tests</li></ul> <b>External modules</b><br>No changes  |
| <b>02.36.78</b> | Sep, 10th 2021 | <ul style="list-style-type: none"><li>▪ Fixed shut down procedure that in some devices didn't working</li></ul> <b>External modules</b><br>No changes  |
| <b>02.36.55</b> | Jun, 17th 2021 | <ul style="list-style-type: none"><li>▪ Improved GPS switch ON procedure to prevent the "GPS ERROR" issue</li></ul> <b>External modules</b><br>No changes  |
| <b>02.36.32</b> | Apr 27th 2021  | <ul style="list-style-type: none"><li>▪ Improved GPS data time synchronization</li><li>▪ Fixed channels acquisition name that caused issue with Race Studio Analysis mathematical channels</li></ul> <b>External modules</b><br>No changes |
| <b>02.36.21</b> | Apr 9th 2021   | <ul style="list-style-type: none"><li>▪ Fixed missed system switch on events</li><li>▪ Fixed bad display reset events</li></ul> <b>External modules</b><br>No changes  |

## MyChron5S Release history

| Version         | Date          | Change/additions   |
|-----------------|---------------|--|
| <b>02.36.19</b> | Apr 2nd 2021  | <ul style="list-style-type: none"><li>■ Improved GPS initialization</li><li>■ Fixed unexpected system cycle of restart when the internal battery is charged and the external battery is connected</li><li>■ Fixed temperature channels visualization in custom page (sometimes missing, blank value when digits number was greater than 3)</li></ul> <p><b>External modules</b></p> <p>No changes</p>  |
| <b>02.34.43</b> | Jan 19th 2021 | <ul style="list-style-type: none"><li>■ Fixed temperatures on display visualization when two sensors with the same function are set (e.g. EGT1/EGT2)</li><li>■ Fixed selected track name visualization on display</li><li>■ Improved RPM measure calculation</li><li>■ Improved display management in case of electro-magnetic noise situations</li></ul> <p><b>External modules</b></p> <p>No changes</p>   |
| <b>02.34.34</b> | Nov 13th 2020 | <ul style="list-style-type: none"><li>■ Fixed bug that could cause half RPM value</li><li>■ Fixed temperature max/min values in resume lap page and in data recall</li></ul> <p><b>External modules</b></p> <p>No changes</p>  |
| <b>02.34.24</b> | Oct 14th 2020 | <ul style="list-style-type: none"><li>■ Improved GPS status visualization in GPS track page</li><li>■ Added missing "Auto" mode in backlight menu</li><li>■ Added "Rec with GPS speed" in debug mode menu</li><li>■ Fixed bug on RPM acquisition that caused RPM calculated as half of the true value</li><li>■ Fixed track autolearning enable/disable in GPS track page</li><li>■ Fixed alarms menu setup</li><li>■ Fixed unit measure conversion of temperatures in data recall pages</li><li>■ Fixed data recall for Oval Race mode</li></ul> <p><b>External modules</b></p> <p>No changes</p> |