



## Solo 2 DL Release history

---

Version	Date	Change/additions
<b>02.26.06</b>	Oct, 5th 2018	<ul style="list-style-type: none"><li>▪ Fixed bug on backlight set in OFF mode</li><li>▪ Fixed power off for external modules when SOLO2 DL is in charging mode</li><li>▪ Fixed bug on Digital output priority handling</li></ul> <p><b>External modules</b></p> <p>No changes</p>



## Solo 2 DL Release history

Version	Date	Change/additions
<b>02.24.05</b>	Sep, 21st 2018	<ul style="list-style-type: none"><li>▪ Custom pages with pressure channels: unit of measure is selectable for each individual channel</li><li>▪ Performance race: fixed missing performance entry in data recall</li><li>▪ Fixed bug in led bar handling with predictive lap time</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.22.81</b>	Jul, 26th 2018	<ul style="list-style-type: none"><li>▪ Fixed power consumption in low power mode (board REV00)</li><li>▪ Fixed multiplexed CAN protocols management</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.22.67</b>	Jun, 29th 2018	<ul style="list-style-type: none"><li>▪ Added automatic start data recall at the end of the new test recorded</li><li>▪ Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior</li><li>▪ Fixed bug in System Info menu in "Hw revision" text display</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.22.65</b>	Jun, 22nd 2018	<ul style="list-style-type: none"><li>▪ Improved suspend/powerup handling</li><li>▪ Support for board revisions C and E</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.22.58</b>	May, 31st 2018	<ul style="list-style-type: none"><li>▪ Support of k-line protocols</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.22.52</b>	May, 18th 2018	<ul style="list-style-type: none"><li>▪ Added "All Laps" data recall page and "Speed graph with track" data recall page</li><li>▪ Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot</li><li>▪ Fixed issue that, sometimes, after a shut down of the system, didn't allow to switch on again the Solo 2 DL</li></ul> <p><b>External modules</b></p> <ul style="list-style-type: none"><li>▪ <b>25.47</b> Lambda</li></ul>