



Solo 2 Release history

| Version | Date | Change/additions |
|-----------------|----------------|--------------------------------------------------------------------------------------------|
| 02.36.81 | Sep, 22th 2021 | ▪ Fixed accelerometers, gyros and magnetometers channels not working in some devices |
| 02.36.76 | Sep, 10th 2021 | ▪ Production needs ▪ Fixed accelerometers, gyros and magnetometers channels acquisition |
| 02.36.34 | Jun, 11th 2021 | ▪ Improved GPS switch on procedure to prevent the "GPS ERROR" issue |
| 02.36.18 | Apr, 2nd 2021 | ▪ Improved GPS inzialization ▪ Added 2 and 5 minutes to Auto-Off setup time in menu |
| 02.34.29 | Nov, 25th 2020 | ▪ Production requirements |

Solo 2 Release history

| Version | Date | Change/additions |
|-----------------|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 02.32.86 | Aug, 21st 2020 | <ul style="list-style-type: none">▪ Signalling of expansions/Wi-Fi: the two upper left shiftlights blink blue▪ Fix missing data recall graph |
| 02.32.74 | Jun, 15th 2020 | <ul style="list-style-type: none">▪ Fixed powerup bug that could cause the system to reset (indicated by red LED blinking slowly) |
| 02.32.72 | Jun, 9th 2020 | <ul style="list-style-type: none">▪ Japanese language update▪ Improved timing of RS232/K-line communication (it helps with some ECU protocols)▪ Added Hour/Date info from GPS tracks▪ Added reference speed used to calculate odometers |
| 02.32.57 | Mar, 17th 2020 | <ul style="list-style-type: none">▪ Minor stability improvements |
| 02.32.52 | Mar, 9th 2020 | NOTE: production-only release <ul style="list-style-type: none">▪ Improved handling of poweroff after fast charge |
| 02.32.49 | Feb, 13th 2020 | NOTE: production-only release <ul style="list-style-type: none">▪ Improved battery handling |
| 02.30.10 | Jun, 12th 2019 | <ul style="list-style-type: none">▪ Fixed bug locking the device in data recall▪ AIM CAN network improvements |
| 02.30.04 | May, 2nd 2019 | <ul style="list-style-type: none">▪ Added Feet measure unit when mph unit is set for speed in track width setting menu |
| 02.30.02 | Apr, 19th 2019 | <ul style="list-style-type: none">▪ Improved K-line protocols management▪ Added open tracks management▪ Added manual track creation on device▪ Added data garbage in menu▪ Added track width setting in menu▪ In data recall added min speed in best lap page and in all laps page |

Solo 2 Release history

| Version | Date | Change/additions |
|-----------------|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 02.26.50 | Jan, 18th 2019 | <ul style="list-style-type: none">▪ Performance Race Mode: fix wrong units of measurement in data recall page (MPH and ft were shown but values were in km/h and m) |
| 02.26.38 | Dec, 14th 2018 | <ul style="list-style-type: none">▪ Fixed calculated Performance Time▪ Fixed "+/- Best Time" display visualization▪ Added "laptime resume visualization" crossing the finish (it can be disabled by menu option) |
| 02.26.06 | Oct, 5th 2018 | <ul style="list-style-type: none">▪ Fixed bug on backlight set in OFF mode▪ Fixed bug on Digital output priority handling |
| 02.24.05 | Sep, 21st 2018 | <ul style="list-style-type: none">▪ Custom pages with pressure channels: unit of measure is selectable for each individual channel▪ Performance race: fixed missing performance entry in data recall▪ Fixed bug in led bar handling with predictive lap time |
| 02.22.81 | Jul, 26th 2018 | <ul style="list-style-type: none">▪ Fixed power consumption in low power mode (board REV00) |
| 02.22.67 | Jun, 29th 2018 | <ul style="list-style-type: none">▪ Added automatic start data recall at the end of the new test recorded▪ Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior▪ Fixed bug in System Info menu in "Hw revision" text display |
| 02.22.65 | Jun, 22nd 2018 | <ul style="list-style-type: none">▪ Improved suspend/powerup handling▪ Support for board revisions C and E |
| 02.22.52 | May, 18th 2018 | <ul style="list-style-type: none">▪ Added "All Laps" data recall page and "Speed graph with track" data recall page▪ Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot▪ Added acquisition of accelerometer and gyroscope channels |