





MXm Release history

Page 1

Version	Date	Change/additions
02.36.76	Sep, 10th 2021	■ Fixed digital speed parameters from RS3 configuration setup External modules No changes
02.36.55	Jun, 17th 2021	■ Improved GPS switch ON procedure to prevent the "GPS ERROR" issue External modules No changes
02.36.18	Apr, 2nd 2021	 Improved GPS inizialization Fixed bug that could cause half RPM value External modules No changes








MXm Release history

Page 2

Version	Date	Change/additions
02.34.29	Nov, 4th 2020	■ Fixed "Track learning" enable/disable on display GPS page
		External modules
		No changes
02.32.78	Jul, 10th 2020	■ Fixed RPM issue due to wrong RPM factor handling
		External modules
		No changes
02.32.72	Jun, 9th 2020	■ Japanese language update
		■ Improved timing of RS232/K-line communication (it helps with some ECU protocols)
		Added Hour/Date info from GPS tracks
		Added reference speed used to calculate odometers
		External modules
		No changes
	l 124 2010	
02.30.10	Jun, 12th 2019	Fixed bug locking the device in data recallAIM CAN network improvements
		Fixed the calibration of the Expansion channels
		External modules
		40.62 Channel Expansion/TC Hub
		■ 35.61 GPS Module
02.30.02	Apr, 19th 2019	■ Improved K-line protocols management
		Added open tracks management
		External modules
		No changes
02.26.56	Mar, 20th 2019	■ Fix current measurement of power outputs
		External modules
		No changes







MXm Release history

Page 3

Version	Date	Change/additions
02.26.55	Mar, 14th 2019	 Improved ADC accuracy Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones) Fix bug on clear alarm by keypress External modules No changes
02.26.50	Jan, 18th 2019	 Fix: odometers not counting and communication lockup issues ECU: support Adaptronics and Motec M4 ECU drivers External modules No changes
02.26.12	Oct, 30th 2018	 Support for CAN Optical Lap (IRM_42) CAN network fixes 100Hz CAN output management Fixed digital speed External modules No changes
02.26.06	Oct, 5th 2018	 Fixed bug on backlight set in OFF mode Fixed bug on Digital output priority handling External module 25.47 Lambda
02.24.04	Sep, 21st 2018	■ Support for RS232 protocols
02.22.93	Sep, 4th 2018	 Dashes visualization ("—") when last laptime is not available Added in menu "Restart Gear Calib" if gear have been already calculated Fix on Data Recording using Race Studio 3 Standard Condition Fix on visualized unit of measure